

Visual Amenity

The form, contrasting aspects and reflective aspects of mining structures are visually softened to blend in with the surrounding landscape

Viewpoint



Current (2017)



- Site views under the existing perimeter tree canopy
- Recent re-vegetation in adjacent paddock and perimeter tree rows starting to be visible
- Foreground colour and depth perception changes with seasonal vine leaf cover

End of Construction



- Construction hoarding / fencing in place
- No planting
- Silo in view

Petaluma Winery

Visible Elements

- Ore silo
- Silo conveyor
- Loading shed

Artwine Cellar Door

Visible Elements

- Mine Water Dam
- Maintenance track
- Revegetation



- Site views framed by cellar door carpark trees
- Open grassed paddock and existing tree line is visible



- Construction hoarding / fencing in place
- No planting

Bird in Hand Winery

Visible Elements

- Ore silo
- Stormwater Dam
- Revegetation



- Site views under the existing perimeter tree canopy
- Recent re-vegetation in adjacent paddock and perimeter tree rows starting to be visible
- Foreground colour and depth perception changes with seasonal vine leaf cover



- Construction hoarding / fencing in place
- No planting
- Silo in view

Ridge Road

Visible Elements

- Ore Silo (very small)



- 2019 photograph
- View through existing large trees to site



- Silo in view in the distance
- Silo colour to be confirmed and shown for illustration purposes only
Final colour subject to community input

BIHGP Entry

Visible Elements

- Entry Road
- Fencing
- Stormwater infrastructure
- New planting



- 2019 photograph
- Farm gate and rubble entry verge
- Seasonal grass cover in verge
- Views to open paddock



- New entry road to allow vehicle turn path
- New fence around entry (similar to Polo Club)
- Stormwater infrastructure and scour protection in verge
- Road and verge linemarking
- Construction hoarding / fencing still in place
- No planting within construction zone