

Operations

1 year vegetation growth

Closure



- Run of Mine silo visible above tree canopy
- Silo colour to be confirmed and shown for illustration purposes only
Final colour subject to community input
- Initial plantings established



- Re-vegetation at perimeter partially obscures views into the site



- Run of Mine silo is removed
- Native shrubs, ground-covers & trees established



- Water storage dam and partial views of pump shed are visible
- Dam fringe planting and maintenance track partially visible
- Initial plantings installed



- Batter planting and adjacent re-vegetation partially obscuring dam edge



- Water storage dam with minimal water
- Native shrubs, ground-covers & trees established further



- Run of Mine silo visible above tree canopy
- Silo colour to be confirmed and shown for illustration purposes only
Final colour subject to community input
- Initial plantings established



- Re-vegetation at perimeter partially obscures views into the site



- Run of Mine silo is removed
- Native shrubs, ground-covers & trees established



- Run of Mine silo visible above tree canopy
- Initial plantings established



- Re-vegetation at perimeter partially obscures views into the site



- Run of Mine silo is removed
- Native shrubs, ground-covers & trees established further



- Shade tree avenue established
- Initial plantings established



- Native shrubs, groundcovers & trees



- Entry road and storm water infrastructure retained for future land-use
- Further tree growth